
DTC	C1251/51	PUMP MOTOR IS LOCKED/OPEN CIRCUIT	
		IN PUMP MOTOR GROUND	

# **CIRCUIT DESCRIPTION**

DTC No.	DTC Detecting Condition	Trouble Area
C1251/51	ABS actuator pump motor is not operating normally during initial check.	ABS pump motor

# **WIRING DIAGRAM**



2004 COROLLA (RM1037U)

Author: Date: 495

#### INSPECTION PROCEDURE

HINT:

Start the inspection from step 1 in case of using the hand-held tester and start from step 2 in case of not using hand-held tester.

### 1 INSPECT BRAKE ACTUATOR ASSY

- (a) Select the DATALIST mode on the hand-held tester.
- (b) Check the operation sound of the ABS pump motor when operating it with the hand–held tester.


The operation sound of the ABS pump motor should be heard.



PROCEED TO NEXT CIRCUIT INSPECTION SHOWN ON PROBLEM SYMPTOMS TABLE

NG

### 2 INSPECT SKID CONTROL ECU TERMINAL VOLTAGE(+BM TERMINAL VOLTAGE)



- (a) Disconnect the skid control ECU connector.
- (b) Measure the voltage between terminal +BM (24) and GND (23) of skid control ECU harness side connector.

The operation sound of the ABS pump motor should be heard.

NG

REPAIR OR REPLACE HARNESS OR CONNECTOR

**REPLACE BRAKE ACTUATOR ASSY**