work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$30,720, or \$240 per airplane.

The total cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Should replacement of any of the flight control rods be necessary, the number of work hours and the cost of required parts would vary according to the type of replacement accomplished. In a "worst case scenario" (both subject rods needing replacement), the cost of parts would be approximately \$6,000 per airplane. Labor necessary to accomplish replacement of a rod(s) would vary from 54 to 87 work hours, at an average labor rate of \$60 per work hour.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is

contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

95-03-08 Aerospatiale: Amendment 39-9145. Docket 94-NM-84-AD.

Applicability: Model ATR42–300 and -320 series airplanes on which Aerospatiale Modification 02723 has not been installed, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no

case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent problems associated with corrosion of the flight control rods, which could compromise the required strength of these items, accomplish the following:

- (a) Within 18 months after the effective date of this AD, visually inspect the elevator trim and rudder trim fail-safe rods to determine the model and the orientation of the open end of the rod, in accordance with Aerospatiale Service Bulletin ATR42–27–0071, dated February 23, 1994.
- (1) If a SARMA-type rod is installed at either of these locations, prior to further flight, replace that rod with a modified rod, in accordance with Aerospatiale Service Bulletin ATR42–27–0049, Revision 2, dated May 16, 1991.
- (Ž) If a TAC-type rod is installed at either of these locations, and if the open end of the rod is oriented in any direction other than downwards, prior to further flight, accomplish the reverse installation procedures specified in Aerospatiale Service Bulletin ATR42–27–0048, Revision 2, dated May 16, 1991.
- (b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.
- **Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM–113.
- (c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.
- (d) The actions shall be done in accordance with the following Aerospatiale Service Bulletins, which contain the specified effective pages:

Service bulletin number and date	Page No.	Revision level shown on page	Date shown on page
Revision 2	1, 2, 4–6	2	June 22, 1990. Nov. 21, 1990. May 16, 1991. Sept. 14, 1990.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained

from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue,

SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.