- (a) Remove from service CECO engine fuel pumps with greater than 1,300 hours time in service (TIS) since new or overhaul on the effective date of this airworthiness directive (AD), within the next 100 hours TIS after the effective date of this AD, in accordance with AlliedSignal Engines Service Bulletin (SB) No. LT101–73–20–0165, Revision 1, dated January 3, 1995, or previous revision.
- (b) Remove from service CECO engine fuel pumps with greater than 850 hours TIS but less than or equal to 1,300 hours TIS since new or overhaul on the effective date of this AD, within the next 150 hours TIS after the effective date of this AD, in accordance with AlliedSignal Engines SB No. LT101–73–20–0165, Revision 1, dated January 3, 1995, or previous revision.
- (c) Remove from service CECO engine fuel pumps with less than or equal to 850 hours TIS since new or overhaul on the effective date of this AD, within the next 300 hours TIS after the effective date of this AD, or prior to accumulating 1,000 hours TIS since

new or overhaul, whichever occurs first, in accordance with AlliedSignal Engines SB No. LT101–73–20–0165, Revision 1, dated January 3, 1995, or previous revision.

(d) Thereafter, remove from service CECO engine fuel pump at intervals not to exceed 900 hours TIS since the last inspection in accordance with the Accomplishment Instructions of AlliedSignal Engines SB No. LT101–73–20–0165, Revision 1, dated January 3, 1995, or previous revision.

(e) Engine fuel pumps that exhibit wear beyond the limits specified in AlliedSignal Engines SB No. LT101–73–20–0165, Revision 1, dated January 3, 1995, or previous revision, may not be returned to service.

(f) For the purpose of this AD, a serviceable part is defined as a new part, or a part that has been inspected by CECO in accordance with AlliedSignal Engines SB No. LT101–73–20–0165, Revision 1, dated January 3, 1995, or previous revision, and that has not yet accumulated 900 hours TIS since new, or since inspection by CECO.

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. The request should be forwarded through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

- (h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.
- (i) The actions required by this AD shall be done in accordance with the following service bulletin:

Document No.	Revision	Pages	Date
AlliedSignal Engines SB No. LT101–73–20–0165	1	1–3	January 3, 1995.
Total Pages: 3. Chandler Evans SB No. 73–13 Total Pages: 5.	1	1–5	January 3, 1995.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from AlliedSignal Engines, 550 Main Street, Stratford, CT 06497; telephone (203) 385–2000. Copies may be inspected at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

- (j) This amendment supersedes priority letter AD 94–19–01, issued September 2, 1994.
- (k) This amendment becomes effective on May 10, 1995.

Issued in Burlington, Massachusetts, on April 17, 1995.

James C. Jones,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 95-10134 Filed 4-21-95; 11:19 am]

BILLING CODE 4910-13-P

DEPARTMENT OF LABOR

Occupational Safety and Health Administration

29 CFR Part 1952

[Docket No. T-026]

Michigan State Plan: Approval of Revised Compliance Staffing Benchmarks

AGENCY: Department of Labor, Occupational Safety and Health Administration (OSHA).

ACTION: Final Rule: approval of revised State compliance staffing benchmarks.

SUMMARY: This document amends agency regulations to reflect the Assistant Secretary's decision to approve revised compliance staffing benchmarks for the Michigan State plan. **EFFECTIVE DATE:** April 25, 1995.

FOR FURTHER INFORMATION CONTACT: Richard Liblong, Director, Office of Information and Consumer Affairs, Occupational Safety and Health Administration, U.S. Department of Labor, Room N–3637. 200 Constitution Avenue NW., Washington, D.C. 20210, (202) 219–8148.

SUPPLEMENTARY INFORMATION:

Background

Section 18 of the Occupational Safety and Health Act of 1970 ("the Act," 29 U.S.C. 651 et seq.) provides that States which desire to assume responsibility for developing and enforcing occupational safety and health standards may be so by submitting, and obtaining Federal approval of, a State plan. Section 18(c) of the Act sets forth the statutory criteria for plan approval, and among these criteria is the requirement that the State's plan provide satisfactory assurances that the state agency or agencies responsible for implementing the plan have "* * the qualified personnel necessary for the enforcement of * * * standards," 29 U.S.C. 667(c)(4).

A 1978 decision of the U.S. Court of Appeals and the resultant implementing order issued by the U.S. District Court for the District of Columbia (AFL-CIO v. Marshall, C.A. No. 74–406) interpreted this provision of the Act to require States operating approved State plans to have sufficient compliance personnel necessary to assure a "fully effective" enforcement effort. The Assistant Secretary of Labor for Occupational Safety and Health (the Assistant Secretary) was directed to establish "fully effective" compliance staffing levels, or benchmarks, for each State plan.

In 1980 OSHA submitted a *Report to* the Court containing these benchmarks and requiring Michigan to allocate 141 safety and 225 health compliance personnel to conduct inspections under the plan. Attainment of the 1980 benchmark levels or subsequent