

request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent jamming of the elevator and aileron disconnect handles, accomplish the following:

(a) Within 600 flight hours after the effective date of this AD, or within 6 months after the effective date of this AD, whichever occurs first, perform an inspection to determine if a travel stop (screw) is installed at the flight control assembly, in accordance with Jetstream Service Bulletin J41-27-036, dated September 2, 1994.

(1) If no travel stop is found to be installed, prior to further flight, install a new travel stop in accordance with the service bulletin. After installation, accomplish paragraph (a)(2) of this AD.

(2) If such a travel stop is installed, prior to further flight, perform a rotation to determine the security of the travel stop, in accordance with the service bulletin.

(i) If the travel stop is found to be properly secured, no further action is required by paragraph (a) of this AD.

(ii) If the travel stop is found to be loose, prior to further flight, remove it and perform an inspection to detect damage in accordance with the service bulletin. If any damage is found, replace the travel stop with a new travel stop, in accordance with the service bulletin. After replacement, repeat the requirements of paragraph (a)(2) of this AD.

(b) After accomplishment of paragraph (a) of this AD, prior to further flight, accomplish paragraphs (b)(1), (b)(2), and (b)(3) of this AD, in accordance with Jetstream Service Bulletin J41-27-036, dated September 2, 1994.

(1) Apply Loctite Superfast 290 to the travel stop;

(2) Permanently mark the flight control assembly; and

(3) Perform a functional test of the aileron and elevator disconnect systems and set them to the locked position.

**Note 2:** Procedures for installing a protective spiral wrap cover are contained in Jetstream Service Bulletin J41-27-036, dated September 2, 1994. This installation is recommended, but is not required by this AD.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

**Note 3:** Information concerning the existence of approved alternative methods of

compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The actions shall be done in accordance with Jetstream Service Bulletin J41-27-036, dated September 2, 1994. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on August 23, 1995.

Issued in Renton, Washington, on July 13, 1995.

**James V. Devany,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 95-17708 Filed 7-21-95; 8:45 am]

BILLING CODE 4910-13-U

#### 14 CFR Part 39

[Docket No. 94-NM-176-AD; Amendment 39-9315; AD 95-11-11 R1]

#### **Airworthiness Directives; McDonnell Douglas Model DC-10-10, -15, -30, -40, and KC-10 (Military) Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This amendment clarifies information in an existing airworthiness directive (AD), applicable to certain McDonnell Douglas DC-10 and KC-10 series airplanes, that currently requires repetitive eddy current inspections to detect fatigue cracking of the pylon aft bulkhead flange, upper pylon box web, fitting radius, and adjacent tangent areas; and repair, if necessary. The actions specified in that AD are intended to prevent failure of the wing pylon aft bulkhead due to fatigue cracking, which could lead to separation of the engine and pylon from the airplane. This amendment clarifies the requirements of the current AD by specifying the type of initial and repetitive inspections that must be conducted. This amendment is prompted by communications received from affected operators that the current requirements of the AD are unclear.

**DATES:** Effective July 3, 1995. -

The incorporation by reference of certain publications listed in the regulations was approved previously by the Director of the Federal Register as of July 3, 1995 (60 FR 28524, June 1, 1995).

**ADDRESSES:** The service information referenced in this AD may be obtained from McDonnell Douglas Corporation, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Technical Publications Business Administration, Dept. C1-L51 (2-60). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, Transport Airplane Directorate, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### **FOR FURTHER INFORMATION CONTACT:**

Maureen Moreland, Aerospace Engineer, Airframe Branch, ANM-120L, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Boulevard, Lakewood, California 90712; telephone (310) 627-5238; fax (310) 627-5210.

**SUPPLEMENTARY INFORMATION:** On May 19, 1995, the FAA issued AD 95-11-11, amendment 39-9244 (60 FR 28524, June 1, 1995), which is applicable to certain McDonnell Douglas Model DC-10-10, -15, -30, -40, and KC-10 (military) series airplanes. That AD requires repetitive eddy current inspections to detect fatigue cracking of the pylon aft bulkhead flange, upper pylon box web, fitting radius, and adjacent tangent areas; and repair, if necessary. That action was prompted by fatigue cracking found in the wing pylon aft bulkheads on two airplanes. The actions required by that AD are intended to prevent failure of the wing pylon aft bulkhead due to fatigue cracking, which could lead to separation of the engine and pylon from the airplane. -

Since the issuance of that AD, the FAA has received communications from affected operators that the requirements for the eddy current inspections, as iterated in the AD, are unclear. Specifically, these operators have indicated that the referenced McDonnell Douglas Alert Service Bulletin A54-106, Revision 2, dated November 3, 1994, recommends that "eddy current bolt hole inspections" and "eddy current surface probe inspections" be conducted of the subject areas; however, the AD indicates that merely an "eddy current inspection" is required. Additionally, these operators point out that the service bulletin recommends