

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Bombardier Inc. (Formerly Canadair):
Docket 94–NM–239–AD.

Applicability: Model CL–600–1A11 (CL–600) series airplanes, serial numbers 1004 through 1085 inclusive; Model CL–600–2A12 (CL–601) series airplanes, serial numbers 3001 through 3066 inclusive; Model CL–600–2B16 (CL–601–3A, –3R) series airplanes, serial numbers 5001 through 5150 inclusive; Model CL–500–2B19 (Regional Jet Series 100) series airplanes, serial numbers 7003 through 7040 inclusive; equipped with Sundstrand air driven generator (ADG) uplock assembly having part number 721863, 721863A, or 721863B; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (c) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the shaft pin, which could lead to the inability of the pilot to manually deploy the air driven generator (ADG) when necessary (i.e., when an airplane's primary electrical power sources are lost and the ADG fails to deploy automatically), accomplish the following:

(a) For Model CL–600–2B19 (Regional Jet Series 100) series airplanes equipped with Sundstrand ADG uplock assembly having P/

N 721863B: Accomplish paragraphs (a)(1), (a)(2), and (a)(3), in accordance with Canadair Alert Service Bulletin S.B. 1601R–24–019, Revision 'A', dated August 9, 1994.

(1) Within 600 flight hours after the effective date of this AD, perform an inspection to verify the proper operation of the uplock latch of the ADG, in accordance with the Accomplishment Instructions of the service bulletin. If the uplock latch cannot be activated, prior to further flight, replace the uplock latch with a serviceable part in accordance with the service bulletin.

(2) Within 12 months after the effective date of this AD, replace the uplock assembly with a modified uplock assembly, in accordance with the Accomplishment Instructions of the service bulletin.

(3) After accomplishment of paragraph (a)(1) or (a)(2) of this AD, perform a rigging inspection in accordance with the Accomplishment Instructions of the service bulletin.

(b) For Model CL–600–2A12, CL–2B16, and CL–600–1A11 series airplanes: Accomplish paragraphs (b)(1), (b)(2), and (b)(3), in accordance with Canadair Service Bulletin 600–0638, dated April 25, 1994 (for Model CL–600–1A11 series airplanes), or Canadair Service Bulletin 601–0430, dated April 25, 1994 (for Model CL–600–2A12 and –2B15 series airplanes), as applicable.

(1) Within 150 flight hours after the effective date of this AD, perform an inspection to verify the proper operation of the uplock latch of the ADG, in accordance with the Accomplishment Instructions of the applicable service bulletin. If the uplock latch cannot be activated, prior to further flight, replace the uplock latch with a serviceable part, in accordance with the applicable service bulletin.

(2) Within 12 months after the effective date of this AD, replace the uplock assembly with a modified uplock assembly, in accordance with the Accomplishment Instructions of the applicable service bulletin.

(3) After accomplishment of paragraph (b)(1) or (b)(2) of this AD, perform a rigging inspection in accordance with the Accomplishment Instructions of the applicable service bulletin.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA, Engine and Propeller Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on February 13, 1995.

S.R. Miller,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 95–4002 Filed 2–16–95; 8:45 am]

BILLING CODE 4910–13–U

14 CFR Part 39

[Docket No. 94–NM–189–AD]

Airworthiness Directives; Jetstream Model 4101 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Jetstream Model 4101 airplanes. This proposal would require an inspection to determine if a travel stop (screw) is installed at the flight control assembly, and various follow-on actions. This proposal is prompted by a report of failure of the travel stop, which allowed the elevator and aileron disconnect handles to rotate within the housing due to migration of the travel stop from its position. The actions specified by the proposed AD are intended to prevent such migration, which could result in the elevator and aileron disconnect system resetting without the use of the reset button; this condition could lead to jamming of the disconnect handles.

DATES: Comments must be received by March 31, 1995.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–103, Attention: Rules Docket No. 94–NM–189–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041–6029. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Sam Grober, Aerospace Engineer, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton,