PROBLEM SYMPTOMS TABLE

057TH-01

Symptom	Suspected Area	See page
All doors are not operated by driver's door key cylinder interlocked with key	 Door lock control switch Front door lock assy LH Wire harness Integration relay 	05–677
Key confinement prevention function does not work properly (Unlock warning switch circuit)	 Un–lock warning switch assy Front door courtesy lamp switch assy Wire harness Integration relay 	05–682

2004 COROLLA (RM1037U)

Author: Date: 841