
MALFUNCTION IN CLOCK

WIRING DIAGRAM



INSPECTION PROCEDURE

1 INSPECT FUSE

- (a) Check the continuity in CIG fuse.
- (b) Check the continuity in DOME fuse.


NG REPLACE FUSE

ОК

2004 COROLLA (RM1037U)

Author: Date: 831

2 INSPECT HARNESS OR CONNECTOR



- (a) Check voltage.
 - (1) Remove the clock assy with connector still connected.
 - (2) Measure voltage between terminal 1 (+B) of clock assy connector and body ground.

Standard voltage: 10 - 14 V

- (3) Turn the ignition switch to ACC.
- (4) Measure voltage between terminal 4 (ACC) of clock assy connector and body ground.

Standard voltage: 10 - 14 V

- (b) Check continuity.
 - (1) Check continuity Between terminal 2 (E) of clock assy connector and body ground.

OK: Continuity exists



OK

REPLACE CLOCK ASSY

Author: Date: 832