

modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To ensure that the "EXIT" signs for the overwing emergency exit are clearly visible during an evacuation, accomplish the following:

(a) Within 8 months after the effective date of this AD, install two additional "EXIT" signs, one above and between the left-hand overwing emergency exits, and one above and between the right-hand overwing emergency exits, in accordance with Fokker Service Bulletin SBF100-33-015, Revision 1, dated March 21, 1994.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on January 11, 1995.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 95-1133 Filed 1-17-95; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 39

[Docket No. 92-CE-21-AD]

Airworthiness Directives; Glaser-Dirks Flugzeugbau GmbH Model DG-100 Sailplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Supplemental notice of proposed rulemaking (NPRM); Reopening of the comment period.

SUMMARY: This document proposes to revise an earlier proposed airworthiness directive (AD), which would have required inspecting (one-time) the tailplane main fitting on Glaser-Dirks Flugzeugbau GmbH (Glaser-Dirks) Model DG-100 sailplanes to ensure the part is accurately welded, and modifying if not accurately welded. A report of tailplane main fitting failure on one of the affected sailplanes, where the welding did not completely cover the entire wall thickness of the fitting, prompted the proposed action. The previous notice was written against all DG-100's; however, if the sailplane is equipped with a horizontal stabilizer and an elevator instead of a L4 tailplane main fitting (main L4 fitting of the all flying tailplane), the proposed AD should not apply. The proposed action would require the same one-time inspection of the tailplane main fitting, but would exclude those sailplanes equipped with a horizontal stabilizer and an elevator. The proposed actions are intended to prevent loss of control of the sailplane because of tailplane main fitting failure.

DATES: Comments must be received on or before March 27, 1995.

ADDRESSES: Submit comments in triplicate to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 92-CE-21-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Glaser-Dirks Flugzeugbau GmbH, Im Schollengarten 19-20, 7520 Buchsal 4, Germany. This information also may be examined at the Rules Docket at the address above.

FOR FURTHER INFORMATION CONTACT: Mr. Herman Belderok, Project Officer, Sailplanes, Small Airplane Directorate, Airplane Certification Service, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone (816) 426-6932; facsimile (816) 426-2169.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to

the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 92-CE-21-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 92-CE-21-AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Discussion

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain Glaser-Dirks Model DG-100 sailplanes was published in the **Federal Register** on April 22, 1993 (58 FR 21547). That action proposed to require inspecting (one-time) the tailplane main fitting to ensure the part is accurately welded, and modifying if not accurately welded. The inspections and possible modifications were proposed to be accomplished in accordance with Enclosure to Technical Note 301/15, which is a supplement to Glaser-Dirks Technical Note 301/15, dated July 7, 1989.

Interested persons have been afforded an opportunity to participate in the making of this amendment. One comment was received on the content of the proposed AD and no comments were received concerning the FAA's determination of the cost upon the public.

The commenter states that the proposed AD would apply to all Model DG-100 sailplanes. In actuality, the proposal should not apply to those