### §39.13 [Amended]

2. Section 39.13 is amended by adding a new AD to read as follows:

Jetstream Aircraft Limited: Docket No. 92– CE–13–AD.

*Applicability:* Jetstream Models 3101 and 3201 airplanes (serial numbers 757 through 912), certificated in any category.

*Compliance:* Required within the next 50 hours time-in-service after the effective date of this AD, unless already accomplished.

To prevent occupant injury during an emergency situation because of the inability to remove an escape hatch, accomplish the following:

(a) For both Models 3101 and 3201 airplanes, modify the shear fitting at the top of the right-hand escape hatch in accordance with PART A of the ACCOMPLISHMENT INSTRUCTIONS section of Jetstream Service Bulletin (SB) 52–JM 7752, dated December 17, 1991.

(b) For Model 3201 airplanes, modify the shear fitting at the top of the left-hand escape hatch in accordance with PART B of the ACCOMPLISHMENT INSTRUCTIONS section of Jetstream SB 52–JM 7752, dated December 17, 1991.

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance times that provides an equivalent level of safety may be approved by the Manager, Brussels Aircraft Certification Office (ACO), FAA, Europe, Africa, and Middle East Office, c/o American Embassy, B–1000 Brussels, Belgium. The request should be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Brussels ACO.

**Note:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Brussels ACO.

(e) All persons affected by this directive may obtain copies of the documents referred to herein upon request to Jetstream Aircraft Limited, Manager Product Support, Prestwick Airport, Ayrshire, KA9 2RW Scotland; telephone (44–292) 79888; or Jetstream Aircraft Inc., Librarian, P.O. Box 16029, Dulles International Airport, Washington, DC 20041–6029; or may examine these documents at the FAA, Central Region, Office of the Assistant Chief Counsel, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

Issued in Kansas City, Missouri, on February 6, 1995.

#### Michael K. Dahl,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service. [FR Doc. 95–3360 Filed 2–9–95; 8:45 am]

BILLING CODE 4910–13–U

## 14 CFR Part 39

[Docket No. 90-CE-67-AD]

# Airworthiness Directives; Jetstream Aircraft Limited (Formerly British Aerospace, Regional Aircraft Limited) Jetstream Models 3101 and 3201 Airplanes

**AGENCY:** Federal Aviation Administration, DOT. **ACTION:** Supplemental notice of proposed rulemaking (NPRM); reopening of the comment period.

**SUMMARY:** This document reopens the comment period for an earlier proposed airworthiness directive (AD) that proposed to supersede AD 90-13-12, which currently requires modifying the airplane electrical system and revising the emergency procedures section of the Airplane Flight Manual (AFM) on certain Jetstream Aircraft Limited (JAL) Jetstream Models 3101 and 3201 airplanes. The proposal would have retained the requirements of that AD for those airplanes that have not installed modified inverters and restored the inverted transfer function. Since publication of that proposal, the Federal Aviation Administration (FAA) has reexamined various service difficulty reports on the affected airplanes, and determined that the proposed modification is still a valid safety issue (but not an urgent safety of flight issue). Since sufficient time has passed (more than 12 months) since the issuance of the original proposal, the FAA is allowing additional time for the public to comment. The proposed actions are intended to prevent alternating current system failures, which, if not detected and corrected, could result in damage to the airplane navigational systems.

**DATES:** Comments must be received on or before April 14, 1995.

ADDRESSES: Submit comments in triplicate to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 90–CE–67– AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106. Comments may be inspected at this location between 8 a.m. and 4 p.m., Monday through Friday, holidays excepted.

Service information that applies to the proposed AD may be obtained from Jetstream Aircraft Limited, Manager Product Support, Prestwick Airport, Ayrshire, KA9 2RW Scotland; telephone (44–292) 79888; facsimile (44–292) 79703; or Jetstream Aircraft Inc., Librarian, P.O. Box 16029, Dulles International Airport, Washington, DC 20041–6029; telephone (703) 406–1161; facsimile (703) 406–1469. This information also may be examined at the Rules Docket at the address above. **FOR FURTHER INFORMATION CONTACT:** Mr. Raymond A. Stoer, Program Officer, Brussels Aircraft Certification Office, FAA, Europe, Africa, and Middle East Office, c/o American Embassy, B–1000 Brussels, Belgium; telephone (322) 513.3830; facsimile (322) 230.6899; or Mr. John P. Dow, Sr., Project Officer, Small Airplane Directorate, Airplane Certification Service, FAA, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone (816) 426–6932; facsimile (816) 426–2169.

#### SUPPLEMENTARY INFORMATION:

## **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 90–CE–67–AD." The postcard will be date stamped and returned to the commenter.

## Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Central Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 90–CE–67–AD, Room 1558, 601 E. 12th Street, Kansas City, Missouri 64106.

### Discussion

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would