evaluating the effectiveness of the AD action and determining whether additional rulemaking action would be needed.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the rule that might suggest a need to modify the rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report that summarizes each FAA-public contact concerned with the substance of this AD will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this rule must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 94–NM–216–AD." The postcard will be date stamped and returned to the commenter.

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a 'significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT **Regulatory Policies and Procedures (44** FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. App. 1354(a), 1421 and 1423; 49 U.S.C. 106(g); and 14 CFR 11.89.

### §39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**95–02–11 McDonnell Douglas:** Amendment 39–9130. Docket 94–NM–216–AD.

Applicability: Model DC-9-87 (MD-87) series airplanes having factory serial numbers (FSN) 49605 through 49612 inclusive, 49614, 53009 through 53011 inclusive, 53336, 53337, 53340, and 53348; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent severe damage to the airframe in the event of a fire, accomplish the following:

(a) Within 12 months after the effective date of this AD, perform a visual inspection to detect chafing or arcing damage to the wiring of the aft right coatroom, the intercostal, and the recirculation duct assembly near longeron 5 (between stations Y=1078.000 and Y=1098.000), in accordance with McDonnell Douglas MD–80 Service Bulletin 24–151, dated September 29, 1994.

(1) If no damage is found, prior to further flight, modify the wiring installation for the aft right coatroom (reference paragraph 1.C., Condition I, of the service bulletin) in accordance with the procedures described in the service bulletin.

(2) If any damage is found, prior to further flight, modify the wiring installation for the aft right coatroom (reference paragraph 1.C., Condition II, of the service bulletin) in accordance with the procedures described in the service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

**Note 2:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) The inspection and modification shall be done in accordance with McDonnell Douglas MD-80 Serivce Bulletin 24-151, dated September 29, 1994. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from McDonnell Douglas Corporation, P.O. Box 1771, Long Beach, California 90801-1771 Attention: Business Unit Manager, Technical Administrative Support, Dept. L51, M.C. 2-98. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Transport Airplane Directorate, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street NW., suite 700, Washington, DC.

(e) This amendment becomes effective on March 2, 1995.

Issued in Renton, Washington, on January 24, 1995.

### Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 95–2177 Filed 2–14–95; 8:45 am] BILLING CODE 4910–13–U

### DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

### 21 CFR Part 178

[Docket No. 91F-0271]

# Indirect Food Additives: Adjuvants, Production Aids, and Sanitizers

**AGENCY:** Food and Drug Administration, HHS.

### **ACTION:** Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the food additive regulations to provide for the safe use of  $\beta$ , 3(or 4)bis(octadecylthio)cyclohexylethane as an antioxidant for general use in polymeric food-contact articles. This action is in response to a petition filed by Atochem North America, Inc. DATES: Effective February 15, 1995; written objections and requests for a hearing by March 17, 1995.