SOUND QUALITY IS BAD ONLY WHEN CD IS PLAYED(VOLUME IS TOO LOW)

INSPECTION PROCEDURE

- 1 REPLACE CD WITH ANOTHER AND RECHECK
- (a) Replace the CD with another and recheck.
 - (1) Check the installation condition of the radio receiver assembly.

Standard: malfunction disappear.

OK CD FAULTY

NG

CHECK AND REPLACE RADIO RECEIVER ASSY

2004 COROLLA (RM1037U)

Author: Date: 799