







# COMBINATION METER

## HOW TO PROCEED WITH TROUBLESHOOTING

057KA-02

1	Vehicle Brought to Workshop
	
2	Customer Problem Analysis (See page <a href="#">05-639</a> )
	
3	Problem Symptom Confirmation (See page <a href="#">05-647</a> )
	
4	Circuit Inspection (See page <a href="#">05-648</a> - <a href="#">05-668</a> )
	
5	Repair or Replace
	
6	Confirmation Test
	
7	End