

DRIVE SHAFT, PROPELLER SHAFT, AXLE

3009Z-03

PROBLEM SYMPTOMS TABLE

Use the table below to help you find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

Symptom	Suspect Area	See page
Wander	5. Wheel alignment 6. Steering linkage (Loosen or worn) 7. Hub bearing (Worn) 8. Stabilizer bar	26-5 27-3 51-18 30-17 30-24 26-19
Front wheel shimmy	1. Wheel balance 2. Shock absorber 3. Suspension arm lower (Worn) 4. Coil spring 5. Hub bearing (Worn)	26-8 26-13 26-8 30-17 30-24
Noise (Drive shaft)	1. Inbord joint (Worn) 2. Outbord joint (Worn)	30-6 30-6